


1 Unpack & install

1. Carefully remove the tOWER from the box and check the housing for damage.
2. Place the unit in the provided space and lock the wheel-brakes to prevent unintentional rolling.

2 Connection

1. Use the supplied power cord and connect it to the power outlet, at the bottom right of the back of the tOWER.
2. Switch on the tOWER with the main switch on the back-side.



3 Air supply

1. For the sake of the calibration, take care that there is plenty of fresh air. Calibration must be performed before using the machine.
Before starting the calibration process, the room should be flooded with plenty of fresh air. The window or windows are recommended to leave open during the calibration period

4 Calibration

1. Touch the "Settings" button on the touch screen.
2. In the setup menu, press "Sensor Readings" button.
3. Press the "calibrate" button, after confirmation the calibration process will be started, this can take up to 30 minutes.

5 Automatic mode

1. After calibration, the device is ready for use and can be started in automatic mode. Depending on the CO² content the machine will automatically increase the air volume. It is advisable also to activate the UV-C function to achieve the best possible result. Ensuring the best filter effect.



6 Air quality / Scales

1. In the screen you see two types of scales.
 - a. Air quality
Volatile organic compounds (VOC's)
 - b. CO² concentration
The CO₂ sensor can be used to monitor the carbon dioxide concentration of rooms. Carbon dioxide can lead to decreased performance, fatigue and headaches. The human body can not perceive an increasing concentration of CO²

7 Turn off

1. To turn the unit off, press the "OFF" button on the main screen
2. If you plan to leave the device turned off for an extended period of time, it is recommended that you press the power switch off on the back of the device.

8 Questions & Service

Theta Laser GmbH
D- 59368 Werne / Germany
Telefon: +49 (0) 2389/ 962999-0
E-Mail: Info@theta-laser.de

For **Spain** (our agent) :

Logistics Consultancy Spain S.L.,
Avenida Inventor Pedro Cawley 10,
Poligono Industrial "las Salinas" El
Levante, 11500 El Puerto de Santa
Maria. (Cádiz), Spain.
General # +34 956 872 883